

# CABLE INSTALLATION INSTRUCTIONS


(For the XL C300 and XL C400 printers)

Part No. BBF-105955 Rev.\*

## Bill of Materials

Part No.	Description	Quantity
BAN-100254	Screw, Sems #6-32 x .375	2
BAN-105915	Washer, #6 Flat Type B	2
CAP-100273	Clamp, Cable-Round	2

1. Secure coax cable to BNC connector (A) as shown.
2. Route cable through cable clamps B and C.
3. Secure cable clamps in position with #6-32 x 3/8 screw and #6 plain flat washer.



**Rear View of Printer**